

OPERATIONS MANAGER - STATUS REPORT

September 10th, 2026

Treatment Plants

The treatment plants continue to meet constituent discharge requirements on a routine basis.

Collection System

Crews are continuing with regular operations, daily inspections of District lift stations, issuance of correction notices for repairs on private laterals, and inspections on all repairs. Throughout the month, collection staff inspected waterways and the district effluent outfall line after all rain events. In August the district hydraulically cleaned 915 feet of line, and televised 0 feet of line. Line Crews raised and reset 8 manholes in various A.D's

Regulatory Compliance: District is maintaining a >90% compliance currently through the 2026 calendar year...i.e., < 2 SSO's, RWQCB Plant Discharge Requirements.

Facilities & Infrastructure

There have been no discharge violations due to equipment failure

Talking Points

- The District hired a survey and company to do a survey of the Huston Creek Plant Road, in preparation for the scope of work for the asphalt road project planned for this upcoming year.
- Dawn and I met with Pilot Rock and Cloacina a wastewater package treatment plant company. They have been contracted to replace the package plant at the Pilot Rock fire camp, and needed some questions answered as to the flow entering our outfall.
- Dawn and I had an opportunity to meet with the California office of Emergency Services in regards to our erosion control project at Seeley Creek. They have reopened our application for assistance for the erosion repair we completed at Seeley Creek and Huston Creek.